



KSCSTE - CENTRE FOR WATER RESOURCES DEVELOPMENT AND MANAGEMENT

ജലവിഭവ വികസന വിനിയോഗ കേന്ദ്രം







CWRDM WATER QUALITY DIVISION-TESTING LABORATORY

TEST REPORT

No: CWRDM/WQD/WA/2024/10147 (1)

Customer Name and Address:	Date of Issue :23-08-2024			
Sadhbhavana World School	Date of receipt of sample :25-07-2024			
Velliparamba	SRF No :9947 (1)			
Calicut	Test Report No :10147 (1)			
	Analysis Started :25-07-2024			
	Analysis Completed :16-08-2024			
Information Provided by Customer:				
Sample Description	Water Sample (1L, Sample 1-Borewell)	Water Sample (1L, Sample 1-Borewell)		
Sample Drawn by	Party			

TEST RESULTS-CHEMICAL ANALYSIS

SL No.	Parameters	Test Method	Result	Limit of Quantifica tion (LOQ)	Acceptable limit as per IS 10500:2012
1	pH at 25°C	APHA, 2023 (Part 4500 H+ B)	8.81	1.0	6,50-8,50
2	Colour, Hazen	APHA, 2023 (Part 2120 B)	BDL	1.0	5.0
3	Turbidity, NTU	APHA, 2023(Part 2130 B)	0.30	0.20	1.0
4	Total Dissolved Solids, mg/l	APHA, 2023 (Part 2540 C)	238.0	10.0	500.0
5	Total Hardness as CaCO ₃ , mg/l	APHA, 2023 (Part 2340 C)	140.0	2.0	200.0
6	Total Alkalinity as CaCO ₃ , mg/l	APHA, 2023 (Part 2320 B)	158.0	2,0	200,0
7	Chloride as Cl', mg/l	APHA, 2023(Part 4500 Cl' B)	8.0	4.0	250.0
8	Sulphate as SO ₄ ² , mg/l	APHA, 2023 (Part 4500 SO ₄ E)	4.0	1,0	200.0
9	Calcium as Ca, mg/l	APHA, 2021 (Part 3500 Ca B)	43.20	1.0	75.0
10	Magnesium as Mg, mg/l	APHA, 2023 (Part 3500 Mg B)	7.80	1.0	30.0
11	Iron as Fe, mg/l	APHA, 2023 (Part 3500 Fe B)	BDL	0.20	1.0

BDL-Below Detection Level

*******End of the Report******

For CWRDM, Water Quality Division - Testing Laboratory

Tested by

Authorised Signatory

Note: This test report refers only to the particular item(s) submitted for testing. The test results reported in this report are valid at the time of and under the stated condition of measurement. This particular test report cannot be reproduced expect in full, without prior permission of Head. Water Quality Division of the laboratory. Any discrepancies may be brought to the laboratory within 30 days of the testing of the report.

Rummangalam Kazhilenda na 1871 fi anta, India - alama ameri, sanambarana az 1871 dia alam giran

t mall; ed a condenorg, registrares es idm mg. Meloite, www.c. idming

Phone 1911 195 115 1500 248 1601 | Los offers 2 9 1808 24 25

WATER QUALITY DIVISION

CENTRE FOR WATER RESOURCES DEVELOPMENT AND MANAGEMENT KOZHIKODE-673571

TEST RESULTS- BACTERIOLOGICAL ANALYSIS

Sl. No.	Parameters	Test Method	Result	Acceptable limit as per IS 10500:2012
1	Total Coliforms, CFU/100ml	APHA, 2023(Part 9222 B)	Absent	Shall not be detectable in any 100ml sample
2	E.coli, CFU/100ml	APHA, 2023(Part 9222 G)	Absent	Shall not be detectable in any 100ml sample

Note:-

pH of the water sample is found to be greater than the acceptable limit as per IS 10500:2012, Drinking Water Specification. All other tested water quality parameters are found to be within the acceptable limit as per IS 10500:2012, Drinking Water Specification.

*End of the Report******

For CWRDM, Water Quality Division - Testing Laboratory

Tested by

Authorised Signatory

Note: This test report refers only to the particular item(s) submitted for testing. The test results reported in this report are valid at the time of and under the stated condition of measurement. This particular test report cannot be reproduced expect in full, without prior permission of Head - Water Quality Division of the laboratory. Any discrepancies may be brought to the laboratory within 30 days of the issue of the report.

SANITARY CERTIFICATE

I Amitha.K, Health Inspector, Peruvayal Grama Panchayath inspected the Sadhbhavana World School, Velliparamba and it's premises on 10/10/2024 and certify that adequate ventilation, urinal and latrine facilities are provided in the school. Also certify that, safe drinking water is available and other sanitary arrangements are found satisfactory.

This certificate is issued for submitting for CBSE affiliation.

Health Inspector
Peruvayal Gramapanchayath